

Training Protocols for External Learners/Trainers/Visitors



To be able to complete your training you **must** adhere to the below protocols;

1. You must provide a signed COVID-19 Visitor Questionnaire to Ausgrid, either to reception at our Silverwater Learning Centre, or to one of our trainers at our other learning centres.
2. Complete a Rapid Antigen Test (RAT) prior to attending and produce a timestamped photo with their driver's license
 - a. If unable to complete prior to attending, **please arrive 30 minutes early** to complete a RAT.
3. It is recommended you download the Service NSW app prior to attending training.
4. It is recommended you supply your own face mask and wear when required.
5. You are not permitted to enter any other training room other than the one your training is scheduled in.

Upon arrival at the Learning Centre:

1. It is required you;
 - a. **Use hand sanitiser** provided prior to signing in.
 - b. Provide evidence of a **negative RAT** to your trainer.

Requirements during the training session:

1. **Not enter the training room.** Wait outside the room for the trainer to let you in.
2. While in training, you must;
 - a. **Supply your own PPE** – please refer to the table below. Where PPE is not required you must wear appropriate clothing and close toed shoes.

Course	PPE Requirements
Substation Entry	ARC Rated clothing, Nitrile gloves, Safety glasses, Hard hat, Safety boots
Disconnect/Reconnect	ARC Rated clothing, Manual handling, Safety glasses, Hard hat, Face shield, LV Working gloves, Safety
NS146 Pre work Pole Inspection	ARC Rated clothing, Manual handling gloves, Safety glasses, Hard hat, Safety boots
TTDO1570 Insulate LV mains	ARC Rated clothing, Safety glasses, Hard hat, Safety boots, LV gloves and outers, Harness and Lanyard, test lamps, EWP if required.
TTDO1653 OH LV Shorts	ARC Rated clothing, Manual handling gloves, Safety glasses, Hard hat, Safety boots, LV gloves and outers, Harness and Lanyard, test lamps, EWP if required.
TTDO1804 HV Earths up to 132KV	ARC Rated clothing, Manual handling gloves, Safety glasses, Hard hat, Safety boots, LV gloves and outers, Harness and Lanyard, test lamps, EWP if required.
TTDO1400 Streetlighting service worker	ARC Rated clothing, Manual handling gloves, Safety glasses, Hard hat, Safety boots, LV gloves and outers, Harness and Lanyard, test lamps, EWP if required.

Requirements for the end of training;

1. At the end of training, you must;
 - a. Ensure that all your paperwork and assessments are left on the desk for the trainer to collect.
 - b. Take all belongings with you.
 - c. Hand sanitise before and after signing out and returning your pass.